



DONALD T. McMILLAN  
Director

## UTAH GEOLOGICAL AND MINERAL SURVEY

606 BLACK HAWK WAY  
SALT LAKE CITY, UTAH 84108  
(801) 581-6831

SCOTT M. MATHESON  
Governor

GORDON E. HARMSTON  
Executive Director  
Department of Natural Resources

June 1, 1981

### MEMORANDUM

TO: Zella Rasmussen, Councilwoman, Town of Santa Clara

FROM: William Lund, Utah Geological and Mineral Survey

SUBJECT: Landslide affecting Truman Drive, Santa Clara, Washington County, Utah

In response to a request from the Santa Clara City Council, a geologic reconnaissance was made on May 13, 1981, of a small landslide that has developed within the town limits. The failure is located along the bluffs that form the eastern boundary of the Santa Clara River flood plain. Movement of the slide has disrupted Truman Drive causing the pavement to drop and buckle in several places. In addition, the toe of the failure is beginning to impinge on the Santa Clara Field and Canal Company canal. Water is seeping from the slide, and residents in the area have complained of smelling a strong unpleasant odor. Of specific concern during this investigation was the possibility advanced by some council members that irrigation water and sewage effluent migrating in the sub-surface from the town of Ivins, 1½ miles to the northwest, might be causing the ground to fail.

### SCOPE OF WORK

The scope of this investigation included the following:

- A review of geologic, hydrologic, and soils information available on the study area.
- A field reconnaissance of the landslide and its surroundings made in the company of Mr. Reed Wittwer, Santa Clara Town Councilman.
- Examination of stereo aerial photographs covering the slide area.
- A detailed inspection and mapping of the slide.
- Making arrangements with the Southwestern Utah District Health Department to collect water samples for laboratory analysis.
- Preparation of this memorandum and accompanying attachments.

### SETTING

The landslide is located in the NW¼ sec. 16, T. 42 S., R. 16 W., Salt Lake Base Line and Meridian (Attachment 1). The failure occurred where Truman Drive



layer of loose, red-brown, fine, silty sand of probable eolian origin; a moderately-to well-cemented coarse sand and gravel deposit of variable thickness which is undoubtedly of fluvial origin; and the gently north to north-east dipping, purple-gray Chinle Shale that comprises approximately the lower 2/3 of the bluff. The slope failure is confined almost entirely to the shale, the overlying materials becoming involved only when support from below is removed by slippage in the shale unit.

Subsurface hydrologic information on the Santa Clara Bench is limited and generally of poor quality. Wells drilled in T. 42 S., R. 16 W., sections 5, 6, 9, and 16 have encountered water at depths ranging from 9 to 174 feet. The aquifers reported to be supplying those wells include the Kayenta, Moenave, and Chinle Formations, as well as unconsolidated sand and gravel deposits. The few wells that have been drilled through the unconsolidated deposits indicate that these materials differ in thickness from place to place. These differences, especially when they occur over what amounts to relatively short distances (1000-2000 feet) suggest that erosional depressions, perhaps old stream channels, lie buried beneath the surface. What affect those buried features have on the collection and channeling of subsurface waters beneath the bench is not known and could only be determined by test drilling or geophysical studies.


The seep observed near the toe of the landslide issues from disturbed Chinle Shale material. A positive identification on the source of its water cannot be made with the data presently available. However, it appears more likely that the water originates from within the near-site vicinity rather than migrating all the way from Ivins. This conclusion is based upon topographic considerations, the fact that the bedrock beneath the bench dips to the north away from the landslide, and indications that a considerable volume of surface runoff collected and channelized by Truman Drive and the gravelled subdivision road has been diverted onto the slide area. It seems probable that this runoff infiltrating into the plastic shales and clay of the Chinle Formation either triggered or aggravated the slope failure. How much, if any, water is contributed to the seep from the septic system drain fields located a few hundred feet northwest of the slide is not known. Water samples have been collected and tests will be run on the water from the landslide to determine both total water chemistry and if sewage is present. Chemical analyses will also be made on water samples taken from the Ivins irrigation system for comparison with the water draining from the slide. The results of those tests will be forwarded to the town as they become available.

#### CONCLUSIONS AND RECOMMENDATIONS

Based upon the results of this study, the following conclusions and recommendations are made:


1. This landslide is a small rotational slump-type feature that has developed primarily in the Chinle Shale, a rock formation noted for its high shrink/swell and plasticity characteristics.
2. It was not possible during the field reconnaissance to determine the source of the water draining from the landslide, but indications are that it originates from within the near slide vicinity.
3. Chemical analyses of water samples collected from the landslide and the Ivins irrigation system are being made in an attempt to pinpoint the water source. The results of those tests will be forwarded to the city as they become available.

4. Immediate steps that could be taken to help stabilize the landslide include:
- Divert the drainage along Truman Drive and the gravelled subdivision road in such a way that surface runoff is no longer directed onto the landslide.
  - Limit road repairs to the grading of rough spots; imported material should not be used to build up low areas because the additional weight of the fill could cause the slide to move.
  - Heavy truck traffic should be restricted from using Truman Drive where it crosses the landslide.
5. Major improvements to Truman Drive (paving, widening, etc.) or the installation of underground utilities along the roadway should be preceded by a thorough engineering study so that further slope stability problems may either be avoided or properly mitigated.

  
WILLIAM R. LUND  
Site Investigations Section

WRL/co  
Attachment

cc: Steve Labrum, Southwestern Utah District Health Department  
Five County Association of Governments



General location map showing position of landslide and the relationship of Ivins to Santa Clara. Scale 1" = 2000'