

Flesh Flood photos
contact → Paul Guardy
Superintendent of Arches
Bureau of Land Management
27 Aug
until
ph. 259-8161

20 Aug

North HWY 191
Moab, UT

water came w. in bushes of
Arches' road

- cross-section @ U-10

- slope $\approx 1/2^\circ$ $\tan = 0.01455$

- depth $\approx 8'$

- width $43'$

- wetted perimeter (rectangular)
 $59'$

~~all~~ - dr from plunge pool 83 paces ($5 1/2'$ pace)

- bed form sand & bedrock

$\pi =$

- area ≈ 344 sq ft

19 August '87

FLASH FLOOD
Moab area

- pits: Flash flood damage nr Arches
Mill Park entrance

- Damage & erosion of highway *

* (30 ft)

fill caused by
floodwaters, which
were constricted by
bedrock (Rico fs).

UDOT says
big wood
to put
rep on
eroin

- Floodwaters descended a
series of bedrock falls
produced by bedding which
dips @ 10° & ad strikes
@ high oblique to flow direction.
Falls are progressively higher,
from 1 ft to 2 1/2 ft, to the
bend in the channel & throughout
by highway fill. The channel is
constricted by bedrock under
the lower falls and the bend
is rounded then the west
side of the channel is filled
by highway fill which was easily
eroded. The plunge pool &
change in channel direction
probably helped erosion. A
gravel bar was deposited
directly downstream where channel
widens dramatically.

Flash flood (cont.)

- A retaining wall will have to be installed (gabions?) 15-20 ft. high, back-filled to support highway base.
- Floodwaters must have spread out tremendously to have deposited sediment (mud) in Arches parking lot, the retinal channel bypasses the lot.

The highway occupies the gentler part of a wide channel. The culvert routing water from the west side channel was blocked/destroyed (?). The highway could have been covered by erosion on both sides. Most of the water flowed in the eastern channel.

- Flattened vegetation on a bar at the plunge pool indicates water must have been at least 20 ft. deep.