

Rudd Canyon Debris Flow

May 30, 1983

Map of debris flow deposit thickness by W.Carey

Location  $~111^{\circ} 53' 4.95''$   $40^{\circ} 59' 24.3''$

UTAH GEOLOGICAL AND MINERAL SURVEY  
HAZARDS SECTION

N. ←






Figure: Rudd Creek Debris Flow  
Isopach Map; thickness in feet

Investigation: W. Case, 15 June 83

B. Kaliser, Section Chief










Figure 6 Computed outline of Rudd Creek debris flow compared to actual outline of the May, 1983 Farmington, Utah